



- A - Dry
- B - alcohol soaked 24 hr.
- C - gasoline soaked 24 hr.
- D - 10 wt oil soaked - 24 hr.

1 pt H<sub>2</sub>O to gel with PEO SAP  
 Blow torch at (X) for 1 minute on A  
 1 sec on B & 1 sec on C & 15 sec on D.

All started burning at end & percolated  
 B & C started to have full flame

pt gel poured over top each 2x4  
 until fire ceased.

blow torch put at # after  
 removing gel to see how long  
 to restart with coating of gel on  
 2x4.

A started at # but died out  
 D would not start after 15 sec.  
 B " " " " " 5  
 C " " " " " 5

Results - not sure regarding  
 solvent fire on wood.